General Land Office • Original Field Notes

Book Number

774

W.W. Alt - West and South boundaries T 24 N, R 33 W

The images in this file are microfilm images of the notes of W.W. Alt resurveys of portions of the State of Nebraska on file in the Office of the Nebraska State Surveyor located in Lincoln, Nebraska.

The W.W. Alt resurveys began in the mid 1890's and were completed in the early 1900's.

Duplicate

OK

Exd 6-15-1897

...eived with letter from W. W. Alt, U. S. Surveyor, dated February 1, 1897. 12664/1897.

...eived by letter "E" Feb 25th 1898.

189

4—679.

FIELD NOTES

OF THE SURVEY OF

The West + South Boundary

of

Township No. 24 North,

of

Range No. 33 West.

Of the Sixth Principal Meridian,

In the State of Nebraska

AS SURVEYED BY

Willard W. Alt, United States Deputy Surveyor,

Under his Contract No. _____, dated January 26, 1895

Survey commenced June 21, 1896.

Survey completed June 23, 1896.

6—151

Names and Duties of Assistants.

Sidney Blount, Chainman.

Frank H. Pratt, Chainman.

Fred D. Stratton, Flagman.

Albert Niemoth, Mounduman.

Harry P. Knapp, Mounduman

INDEX DIAGRAM.

Township 24 N., *Range* 33 W

5	6	5	4	3	2	1
4	7	8	9	10	11	12
3	18	17	16	15	14	13
3	19	20	21	22	23	24
2	30	29	28	27	26	25
1	31	32	33	34	35	36
	7	7	8	9	10	11

Meanders Page.....

194

Preliminary Oaths of Assistants.

WE, _____ and _____ do solemnly swear that we will well and faithfully execute the duties of chainmen; that we will level the chain upon even and uneven ground, and plumb the tally pins, either by sticking or dropping the same; that we will report the true distances to all notable objects, and the true lengths of all lines that we assist in measuring, to the best of our skill and ability, and in accordance with instructions given us, in the survey of

_____

_____, *Chainman.*

_____, *Chainman.*

Subscribed and sworn to before me this _____ day of _____, 189

SEAL

_____

_____

WE, _____ and _____ do solemnly swear that we will well and truly perform the duties of moundmen in the establishment of corners, according to the instructions given us, to the best of our skill and ability, in the survey of _____

_____

_____, *Moundman.*

_____, *Moundman.*

Subscribed and sworn to before me this _____ day of _____, 189

SEAL

_____

_____

WE, _____ and _____ do solemnly swear that we will well and truly perform the duties of axmen in the establishment of corners and other duties, according to instructions given us, to the best of our skill and ability, in the survey of

_____

_____, *Axman.*

_____, *Axman.*

Subscribed and sworn to before me this _____ day of _____, 189

SEAL

_____

_____

I, _____, do solemnly swear that I will well and truly perform the duties of flagman according to instructions given me, to the best of my skill and ability, in the survey of _____

_____, *Flagman.*

Subscribed and sworn to before me this _____ day of _____, 189

SEAL

_____

_____

6—151

3
95

1
193

West boundary T. 24 N. R. 33 W.

Chains.

I begin at the cor. of Tps. 23 and 24 N. Rs. 33 and 34 W.: which is a cedar post 4 ins. sq. 1 ft. above ground. marked and witnessed as described by J. E. Chambers.
At this cor., at 9h 45m. central Standard Time, or 9h P.M. l.m.t. by my watch, which is 1m fast of central standard time, I observe Polaris in accordance with instructions in the manual. and mark a point on the line thus determined, on a stake driven in the ground N of my station.

June 21, 1896.

June 22: at 8h a.m. l.m.t. I lay off the azimuth of Polaris, 0°45' to the west, and mark the true meridian thus determined by a tack in ——a stake driven in the ground. 2.30 chs. N. of my station.
The magnetic bearing of the true meridian at 8h am. is N. 12°55' W.: the angle thus determined, reduced by the table on page 100 of the manual gives the mean mag. dec. 12°49' E.
From the Tp. cor. I run
North, bet. secs. 31 and 36.
along top of range.

5.00 Begin descent along N. slope.
29.00 Bottom of descent. in narrow valley. E. and W.
31.00 Begin ascent along SW. slope.
40.00 Deposit a charred stake 12 ins. in the ground for ¼ sec. cor.: dig pits 18 x 18 x 12 ins. N. and S. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high. over deposit.
On S. pit. drive cw oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
¼ S. on W. face.
45.00 Top of ascent, on W. face of low range.
75.00 Begin descent, along SW. slope.
80.00 Deposit a charred stake 12 ins. in the ground for cor of secs. 25. 30. 31 and 36: dig pits

Chains.

18 x 18 x 12 ins. in each sec. 4 ft. dist. and raise a mound of earth 4 ft. base 2 ft. high. over deposit.
In S.E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
T 24 N S 30, on NE.
R 33 W S 31. on SE.
S 36. on SW. and
R 34 W S 25. on NW. faces. with 1 notch on S. and 5 notches on N. edges.
Land: broken.
Soil, sandy: 3rd rate.

North, bet. secs. 25 and 30.
Descend gently, over rolling land.
20.00 Bottom of descent, in basin: ascend along SW. slope of range.
40.00 Deposit a charred stake 12 ins. in the ground for ¼ sec. cor.: dig pits 18 x 18 x 12 ins. N. and S. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
In S. pit. drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
¼ S. on W. face.
78.50 Top of ascent. on W. point of range, 100 ft. above valleys: thence along W. face of range, over broken ground.
80.00 Set a cedar post 3 ft. long, 4 ins. sq. with a marked stone 24 ins. in the ground, for cor. of secs. 19. 24. 25. and 30. marked
T 24 N S 19, on NE.
R 33 W S 30. on SE.
S 25. on SW. and
R 34 W S 24. on NW. faces. with 2 notches on S. and 4 on N. edges: dig pits 18 x 18 x 12 ins. in each sec. 5½ ft. dist. and raise a mound of earth 4 ft. base 2 ft. high. W. of cor.
Land: Broken.
Soil, sandy: 3rd rate.

Chains.

North, bet. secs. 19 and 24.
Along N. face of range.
10.00 Begin descent, along N. slope.
39.11 Trail, along railroad.
39.80 Center of track. Burlington and Missouri River railroad: bears N. 85° W., and reverse.
40.00 Deposit 2 pieces of coal, and a small stone 24 ins. in the ground for ¼ sec. cor. the cor. point falling on the railroad right of way. N. 5° E. 56 lks. dist, and S. 5° W. 96 lks. dist. from the cor. point, deposit charred stakes 12 ins. in the ground, for witness cors.: dig pits 18 x 18 x 12 ins. N. and S. of cors. 4 ft. dist. and raise mounds of earth 3½ ft. base, 1½ ft. high, over deposits
In S. pits. drive oak stakes 2 ft. long 2 ins. sq. 12 ins. in the ground. marked
WC. ¼ S., on W. faces.
40.54 Telegraph line: bears N. 85° W.: ascend over low hills.
55.00 Top of ascent, 40 ft.: thence, over broken ground.
80.00 Deposit a marked stone 12 ins. in the ground for cor. of secs. 13. 18. 19. and 24: dig pits 18 x 18 x 12 ins. in each sec. 4 ft. dist. and raise a mound of earth 4 ft. base 2 ft. high. over deposit.
In S.E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground. marked
T 24 N S 18. on NE.
R 33 W S 19. on SE.
S 24, on SW. and
R 34 W S 13. on NW. faces. with 3 notches on N. and S. edges.
Land: broken.
Soil. sandy: 3rd rate.

North, bet. secs. 13 and 18.
Descend over foot hills.
8.00 Bottom of descent, in basin. 30 ft. below cor.

West boundary T. 24 N., R. 33 W.

Chains.

Ascend over broken ground.

21.00 Top of ascent, 75 ft. on bluff; descend over rolling ground, along foot hills sloping to N.E.

40.00 Deposit a marked stone 12 ins. in the ground for 1/4 sec. cor.; dig pits 18 X 18 X 12 ins. N. and S. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
Set S. pit. drive an oak stake 2 ft. long, 2 ins. sq. 12 ins. in the ground, marked
1/4 S., on W. face.

Ascend over rolling ground.

62.00 Top of ascent, 40 ft.; thence over low foot hills.

80.00 Set a cedar post 3 ft. long 4 ins. sq. with a charred stake 24 ins. in the ground, for cor. of secs. 7, 12, 13, and 18, marked
T 24 N S 7, on NE.
R 33 W S 18, on SE.
S 13, on SW. and
R 34 W S 12, on NW. faces, with 4 notches on S. and 2 on N. edges; dig pits 18 X 18 X 12 ins. in each sec. 5½ ft. dist. and raise a mound of earth 4 ft. base, 2 ft. high, W. of cor.
Land: broken.
Soil, sandy; 3rd rate.

North, bet. secs. 7 and 12.
Over rolling hills, ascending gently.

40.00 Deposit a charred stake 12 ins. in the ground for 1/4 sec. cor.; dig pits 18 X 18 X 12 ins. N. and S. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
Set S. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
1/4 S., on W. face.

80.00 Deposit a charred stake 12 ins. in the ground for cor. of secs. 1, 6, 7, and 12; dig pits 18 X 18 X 12 ins. in each sec. 4 ft. dist. and raise a mound of earth 4 ft. base, 2 ft. high, over deposit.

West boundary T. 24 N., R. 33 W.

Chains.

Set S.E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
T 24 N S 6, on NE.
R 33 W S 7, on SE.
S 12, on SW. and
R 34 W S 1, on NW. faces, with 5 notches on S. and 1 notch on N. edges.
Land: rolling.
Soil, sandy; 3rd rate.

North, bet. secs. 1 and 6.
Over rolling table land.

40.00 Deposit a charred stake 12 ins. in the ground for 1/4 sec. cor.; dig pits 18 X 18 X 12 ins. N. and S. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base 1½ ft. high, over deposit.
Set S. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
1/4 S., on W. face.

42.00 Begin gentle descent, over very rolling ground.

45.36 Intersect 6th Standard Parallel, N. 89° 24' W. 13.22 chs. dist. from the 1/4 sec. cor. on S. bdy. of sec. 32, T 25 N., R. 33 W.
Set a cedar post 3 ft. long, 4 ins. sq. with a charred stake 24 ins. in the ground, for closing cor. of Tps. 24 N., Rs. 33 and 34 W. marked
CC T 24 N., on S.
R 33 W S 6, on E. and
R 34 W S 1, on W. faces, with 6 grooves on E., S. and W. faces; dig pits 30 X 24 X 12 ins. crosswise on each line E. and W. 4 ft. and S. of post 8 ft. dist. and raise a mound of earth 5 ft. base 2½ ft. high, S. of cor.
Land: broken.
Soil, sandy; 3rd rate.

June 22, 1896.

West boundary T. 24 N., R. 33 W.

This line runs over broken, and rolling sand hills, its entire length.
There is no timber; the vegetation consisting of Buffalo, and Bunch grasses.

Willard H. Kelly.
U. S. Surveyor.

June 22nd 1896.

— Boundaries of T. 24 N., R. 33 W. —
Latitudes. Departures, and closing errors.

Lines designated	True Bearing	Distances	Latitudes		Departures	
			N.	S.	E.	W.
		Chs	chs.	chs.	chs.	chs.
S. Bdy.	West.	485.10				485.10
W. "	North.	485.36	485.36			
6" Stand.	S. 89° 24' E.	485.86			5.12	485.86
4" Guide	South.	480.13		480.13		
	convergency				.66	
	Totals.		485.36	485.25	486.52	485.10
			485.25			
Error in Lat.			11 lks.		485.10	
Error in Dep.						1.42 chs.

For table of Corrections of Township 23 N., R 33 W., see page 12.

N. bdy. T. 23 N., R. 33 W.

Chains.

At the cor. of Tps. 23 and 24 N., Rs 33 and 34 W., I turn an angle of 90° to the East from the meridian established June 21, and run
East, bet. secs. 6 and 31,
Over broken ground, along top of range.
18.00 Top of range on ridge: thence over ridges and ravines.
40.00 N. 0¼ lk from tangent. Deposit a charred stake 12 ins. in the ground for ¼ sec. cor: dig pits 18x18x12 ins. E. and W. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
In E. pit. drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
¼ S, on N. face.
43.00 Descend along S. face of range, over very broken ground.
80.00 N. 1 lk. from tangent. deposit a charred stake 12 ins. in the ground for cor. of secs. 5. 6. 31. and 32: dig pits 18x18x12 ins. in each sec. 4 ft. dist. and raise a mound of earth 4 ft. base 2 ft. high, over deposit.
In S.E. pit. drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
T 24 N S 32. on NE.
R 33 W S 5. in SE.
T 23 N S. 6. on SW. and
S 31. on NW. faces. with 5 notches on E. and 1 notch on W. edges.
Land: broken.
Soil, sandy; 3rd rate.

East bet., Secs. 5 and 32.
Over very broken ground, along S. face of low range of hills.
4.00 Descend from ridge.
13.00 Pass. or ravine: thence over rolling ground.
37.00 Ridge: thence over very broken ground.

chains.

40.00 N. 2½ lks. from the tangent, deposit a charred stake 12 ins. in the ground. for ¼ sec. cor.: dig pits 18x18x12 ins. E. and W. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
In E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground. marked
¼ S. on N. face.

63.70 Sand bluff or ridge: thence over rolling ground along top of range.

80.00 N. 3½ lks. from the tangent, Set an oak post 3 ft. long, 4 ins. sq. with a charred stake 24 ins. in the ground. for cor. of secs. 4. 5. 32, and 33. marked
T 24 N S 33. on NE.
R 33 W S 4. on SE.
T 23 N S 5. on SW. and
S 32. on NW. faces. with 2 notches on N. and 4 on E. edges; dig pits 18x18x12 ins. in each sec. 5½ ft. dist. and raise a mound of earth 4 ft. base 2 ft. high, N. of cor.
Land: broken.
Soil, sandy: 3rd rate.

East bdy. Secs. 4 and 33.
Over rolling ground.

11.00 Descend.

7.00 Trail, bears N. and S. at bottom of descent. ascend gradually over broken ground.

38.00 Top of ascent. 50 ft.; thence along N. slope, over broken ground.

110.00 N. 6 lks. from the tangent, deposit a charred stake 12 ins. in the ground for ¼ sec. cor.: dig pits 18x18x12 ins. E. and W. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high. over deposit.
In E. bdy. drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground. marked
¼ S., on N. face.

chains.

47.52 Wire fence: bears N. and S.

52.00 Ravine 30 ft. deep; bears N. and S.

80.00 N. 8¼ lks. from the tangent, deposit a charred stake 12 ins. in the ground, for cor. of secs. 3. 4. 33. and 34: dig pits 18x18x12 ins. in each sec. 4 ft. dist. and raise a mound of earth 4 ft. base 2 ft. high. over deposit.
In S.E. pit drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground. marked
T 24 N S 34. on NE.
R 33 W S 3. on SE.
T 23 N S 4. on SW. and
S 33. on NW. faces. with 3 notches on E. and W. edges.
Land: broken.
Soil, sandy: 3rd rate.

East bdy. Secs. 3 and 34.
Over rolling ground, along top of low range.

2.38 Wire fence: bears N. and S.

40.00 N. 11 lks. from tangent. deposit a charred stake 12 ins. in the ground, for ¼ sec. cor.: dig pits 18x18x12 ins. E. and W. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base. 1½ ft. high. over deposit.
In E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
¼ S. on N. face.

58.00 Descend.

62.50 Trail, in pass: bears N. 20° W.; ascend over rolling ground.

80.00 N. 14½ lks. from tangent. set an oak post 3 ft. long, 4 ins. sq. with a charred stake. 24 ins. in the ground. for cor. of secs. 2. 3. 34 and 35 marked
T 24 N S 35. on NE.
R 33 W S 2. on SE.
T 23 N S 3. on SW. and
S 34. on NW. faces. with 4 notches

6/198

10/20N

N. bdy. T. 23 N., R. 33 W.

Chains.

on W. and 2 on E. edges: dig pits 18x18x12 ins. in each sec. 5½ ft. dist. and raise a mound of earth 4 ft. base 2 ft. high N. of cor.
Land: broken.
Soil: sandy: 3rd rate.

East bdy., Secs. 2 and 35.
Ascend along S.E. slope of range.

16.00 Top of ascent: thence along S. face.

35.00 Begin descent, along E. slope, over broken ground.

40.00 N. 18¼ lks. from tangent, deposit a charred stake 12 ins. in the ground for ¼ sec. cor.: dig pits 18x18x12 ins. E. and W. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
In E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
¼ S., on N. face.
Descend over broken ground.

58.00 Trail: bears N. and S., at bottom of descent, ascend gradually along W. slope, over broken ground.

80.00 N. 23 lks. from tangent, deposit a charred stake 12 ins. in the ground, for cor. of secs. 1, 2, 35, and 36: dig pits 18x18x12 ins. in each sec. 4 ft. dist. and raise a mound of earth 4 ft. base 2 ft. high, over deposit.
In S.E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
T 24 N S 36, on NE.
R 33 W S 1, on SE.
T 23 N S 2, on SW. and
S 35, on NW. faces, with 5 notches on W. and 1 notch on E. edges.
Land: broken.
Soil, sandy; 3rd rate.

11/203

N. bdy. T. 23 N., R. 33 W.

Chains.

East bdy., Secs. 1 and 36.
Ascend gradually.

17.00 Top of ascent 20 ft. above cor.: thence along top of low range, over rolling ground.

40.00 N. 27¼ lks. from tangent, deposit a charred stake 12 ins. in the ground, for ¼ sec. cor.; dig pits 18x18x12 ins. E. and W. of cor. 4 ft. dist. and raise a mound of earth 3½ ft. base, 1½ ft. high, over deposit.
In E. pit, drive an oak stake 2 ft. long 2 ins. sq. 12 ins. in the ground, marked
¼ S., on N. face.

80.00 Descend gradually, into ravine or pass.

85.10 Intersect 4th Guide Meridian.
N. 33 lks. from the tangent, set an oak post 3 ft. long, 4 ins. sq., with a charred stake 24 ins. in the ground for closing cor. of Tps. 23 and 24 N., R. 33 W., marked
CC R 33 W. on W.
T 23 N S 1, on S. and
T 24 N S 36, on N. faces with 6 grooves on N., W. and S. faces: dig pits 30x24x12 ins. crosswise on each line, N. and S. 4 ft. and W. of post 8 ft. dist. and raise a mound of earth 5 ft. base 2½ ft. high, N. of cor.
This cor. is N. 6.87 chs. dist. from the old cor. of Tps. 23 and 24 N., Rs. 32 and 33 W., which post I inmert, and mark
T 24 N R 32 W S 31, on NE. and
T 23 N R 32 W S 6, on SE. faces,
with 6 notches on S. and E. edges.
June 23, 1896.

This line runs over broken sand hills, its entire length.
No timber: — Bunch grass.
Soil, sandy, and unfit for cultivation.
Willard N. Alt.
June 23, 1896. U.S. Surveyor.

12
204

6
198

N. Bdy. T. 23 N., R. 33 W.

— Boundaries of T. 23 N., R. 33 W. —
Latitudes, Departures, and closing errors.

Lines designated	True Bearing	Distance	Latitudes		Departure	
			N.	S.	E.	W.
		chs.	chs.	chs.	chs.	chs.
S. Bdy.	S. 89°59' W.	486.08		.14		486.08
W. "	North.	480.00	480.00			
N. "	East.	485.10			485.10	
4th Guide	South.	479.93		479.93		
Convergency					.66	
Totals			480.00	480.07	485.76	486.08
				480.00		485.76
Error in Lat. - - - - - - -				.07 lks.		
Error in Dep. - - - - - - - - - - - - - - -						.32 lks.

For table of boundaries of Township 24 N., R 33 W., see page 6.

13
205

Final Oaths of Deputy Surveyor and his Assistants.

LIST OF NAMES.

A list of the names of the individuals employed by .....

....., United States Deputy Surveyor, to assist in running, measuring, and marking the lines and corners described in the foregoing field notes of the survey of .....

.....

owing the respective capacities in which they acted:

....., *Chainman.*

....., *Chainman.*

....., *Mourdman.*

....., *Moundman.*

....., *Axman.*

....., *Axman.*

....., *Flagman.*

FINAL OATH OF ASSISTANTS.

We hereby certify that we assisted .....

....., United States Deputy Surveyor, in surveying all ose parts or portions of the .....

.....

.....

..... of the ..... base id ..... meridian, ... of ....., which are represented the foregoing field notes as having been surveyed by him and under his direction; and that said survey as been in all respects, to the best of our knowledge and belief, well and faithfully surveyed, and the rner monuments established, according to the instructions furnished by the United States Surveyor eneral for .....

....., *Chainman.*

....., *Chainman.*

....., *Moundman.*

....., *Moundman.*

....., *Axman.*

....., *Axman.*

....., *Flagman.*

.....

bscribed and sworn to before me this .....
day of ....., 189

.....

SEAL

.....

6—151

14
206

6
198

Final Oath of United States Deputy Surveyor.

I, ..., United States Deputy Surveyor, do solemnly swear that, in pursuance of a contract received from ....., United States Surveyor General for ....., bearing date of the ..... day of ....., 189 , I have well, faithfully, and truly, in my own proper person, and in strict conformity with the instructions furnished by the United States Surveyor General for ....., the Manual of Surveying Instructions, and the laws of the United States, surveyed all those parts or portions of .....

.....

.....

.....

..... of the ..... base and ..... meridian, in the ..... of ....., which are represented in the foregoing field notes as having been surveyed by me, and under my direction; and I do further solemnly swear that all the corners of said survey have been established and perpetuated in strict accordance with the Manual of Surveying Instructions, and the special written instructions of the United States Surveyor General for ..... and in the specific manner described in the field notes, and that the foregoing are the original field notes of such survey; and should any fraud be detected, I will suffer the penalty of perjury under the provisions of an Act of Congress approved August 8, 1846.

.....

United States Deputy Surveyor.

Subscribed by said ....., and sworn to before me this ..... day of ....., 189

.....

SEAL.

.....

APPROVAL.

~~Office of the United States Surveyor General~~,

General Land Office, October 22, 1897

The foregoing field notes of the survey of The West and South Boundary of Township No. 24 North, Range No. 33 West of the 6th Principal Meridian, State of Nebraska, as

executed by Willard W. Alk, United States Surveyor under his contract ~~No.~~ ....., dated January 26, 1895, having been critically examined, and the necessary corrections and explanations made, the said field notes, and the surveys they describe, are hereby approved.

Binger Hermann,
Commissioner ~~and Ex-officio United States Surveyor General.~~

I certify that the foregoing transcript of the field notes of the above-described surveys in the State of Nebraska, has been correctly copied from the original notes on file in this office.

Binger Hermann
Commissioner ~~United States Surveyor General.~~
General Land Office.

6—151

General Land Office • Original Field Notes

Book Number

774

W.W. Alt - West and South boundaries T 24 N, R 33 W

The images in this file are microfilm images of the notes of W.W. Alt resurveys of portions of the State of Nebraska on file in the Office of the Nebraska State Surveyor located in Lincoln, Nebraska.

The W.W. Alt resurveys began in the mid 1890's and were completed in the early 1900's.