

NUMBER	LENGTH	AZIMUTH	STRENGTH	30' PENETRATION	ELEVATION ABOVE STRUCTURE	M.S.L. MARKER CLUMP	C.R.P.	WORK ORDER NO.
641.0 R.B.	114'	249 39'	3 ROW-18' CTRS.	STA. 14+46 TO STA. 15+60	959.0	950.6	127-64.1C	
643.2 R.B.	299'	286 27'	3 ROW-18' CTRS.	2 99'	951.0	952.3	127-64.1C	
645.9 R.B.	884'	280 41'	3 ROW-18' CTRS.	684'	964.0	969.0	127-64.1C	
645.9-A R.B.	900'	326 48'	3 ROW-18' CTRS.	STA. 3+00 TO STA. 9+00	964.0	969.0	127-64.1C	
645.6 R.B.	1199'	274 21'	SEE DIKE	SEE DIKE	963.5	968.8	127-64.1C	
645.6-A R.B.	1403'	323 19'	SEE DIKE	STA. 8+50 TO STA. 14+03	963.5	968.8	127-64.1C	
645.2 R.B.	1809'	271 31'	3 ROW-18' CTRS.	SEE DIKE	963.0	968.6	127-64.1C	
645.2-A R.B.	1908'	321 02'	SEE DIKE	STA. 17+0 TO STA. 19+08	963.0	968.6	127-64.1C	
644.7 R.B.	2940'	266 57'	SEE DIKE	SEE DIKE	962.5	968.3	127-64.1C	
643.9 R.B.	3236'	267 52'	SEE DIKE	SEE DIKE	961.1	967.9	127-64.1C	
643.55 R.B.	2050'	SEE DIKE	3 ROW-18' CTRS.	SEE DIKE	961.0	967.6	127-64.1C	
641.7 R.B.	926'	SEE DIKE	1 ROW-S.P.-8' CTRS.	20' PENETRATION	957.0	951.4	127-64.2C	
643.1 R.B.	4420'	SEE DIKE	3 ROW-18' CTRS.	684'	961.0	967.6	127-64.2C	
643.3 R.B.	616'	268 53'	3 ROW-18' CTRS.	684'	961.0	967.6	127-64.2C	
645.3 L.B.	0 57' 00"				963.0	963.0		
646.1 R.B.	400'	281 53'	SEE DIKE	SEE DIKE	964.0	969.0	127-64.1C	
646.0 R.B.	528'	280 45'	SEE DIKE	SEE DIKE	964.0	969.0	127-64.1C	
643.8 L.B.	1054'	50 01'	SEE DIKE	STA. 8+18 TO STA. 8+54	962.0	962.0	127-64.1C	
643.6 L.B.	1246'	47 19'	3 ROW-18' CTRS.	STA. 4+56 TO STA. 17+01	961.0	962.8	127-64.1C	
646.5 R.B.					964.2	969.5	127-64.1C	
646.4 R.B.					964.1	969.4	127-64.1C	
646.4-A R.B.					964.1	969.4	127-64.1C	
646.3 R.B.					964.0	969.2	127-64.1C	
646.2 R.B.					965.0	967.1	127-64.1C	
642.7 L.B.					955.9	966.9	127-64.1C	
642.3 L.B.					955.8	966.7	127-64.1C	

CHART - CONTINUED

STRUCTURE	NUMBER	LENGTH	AZIMUTH	STRENGTH	30' PENETRATION	ELEVATION ABOVE STRUCTURE	M.S.L. MARKER CLUMP	C.R.P.	WORK ORDER NO.
TRAIL	642.3-A L.B.	1134'	SEE DIKE	3 ROW-18' CTRS.	1134'	960.0	966.7	951.7	127-64.1C

60 Standard Revetment 0100 to Sta. 15+00, 1938' Pile Revetment Sta. 61+82 to 81+20 to 9620, also Sta. 81+20 to Sta. 98+58, Standard Revetment (Sta. 35+165 to Sta. 36+20) & 5740' Pile Revetment (Sta. 36+20 to Sta. 93+60, El. 963.0)

- 4 showing Revetment 646.6, 643.1 R.B., 645.3 L.B. and Dikes 646.2, 645.9, 645.9-A, 645.6, 645.6-A, 645.2, 645.2-A, 643.55, 643.55-A, 641.8, R.B. & 644.0, L.B., authorized for construction.
- 4 showing authority for constructing Revetment 646.6 revoked, Dikes 646.3, 646.2, 646.1, & 646.0 for construction, also changed layout for Dikes 645.9 & 645.9-A, all R.B.
- 4 showing 335' of additional Revetment 643.1 R.B. authorized for construction.
- 14 showing Dike 646.3, R.B. rescinded; Dike 646.2, R.B. rescinded and not now authorized for construction or contract or hired labor, also change in strength and penetration of Dikes 646.1, 646.0, R.B. to conform to letter of even date.
- 4 showing layout of Dike 643.9 R.B. changed to conform to letter of even date.
- 5 showing portion of Dikes 643.8 & 643.6, L.B. authorized for construction.
- 5 showing changed length of Standard and Pile Revetment portions of Revetment 645.3, L.B., changed elevation of Dikes 644.0, 643.6, L.B., and changed length and strength of Dikes 643.8 and 643.6, L.B.
- 936 showing changed length & layout of Dike 643.55, R.B., to conform to letter of even date.
- 136 showing changed layout of Dike 643.55-A, R.B. and showing Dike 643.2, R.B. authorized for construction, and showing changed in and alignment of Revetment 643.1 and Long Dike 641.8, R.B.
- 936 showing changed length of Dike 643.55 R.B. and showing Long Dike 641.8 R.B. rescinded and deleted from map.
- 22, 1936 showing Trail Dike 643.55-A, R.B. rescinded and deleted from map, and showing portion of Dike 643.3, R.B. authorized for construction.
- 937 showing changed length of Dike 643.3 R.B., to conform to letter of even date.
- 1937, showing Bank Protection Dike (641.7 R.B.) above 641.5 R.B., authorized for construction.
- 1937, showing Revetment 643.1 R.B. changed from Standard to Pile Revetment, Sta. 65+00 to Sta. 76+33
- 1937, showing changed lengths of Revetments No. 645.3, L.B. & 643.1, R.B.
- 1, 1937, showing changed length of Revetment 643.1 R.B., to conform to letter of even date.

REVISIONS (Cont)

- Jan. 24, 1938 showing changed length of Revetments 645.3 L.B. and 643.1 R.B. Dike 644.0 L.B. deleted from map and Dike Extension 643.6, L.B. authorized for construction. Also changed length of Dike No. 643.8 L.B. Feb. 17, 1938 showing authority for construction of Dike 643.6 (Sta. 17+01 to Sta. 21+76) L.B., and Revetment 643.1 (Sta. 36+70 to Sta. 61+82), L.B., rescinded, to conform to letter of even date.
- April 21, 1938 showing Dike Extension 642.3 and Trail 642.3-A, both L.B., authorized for construction, and Standard Revetment 643.1 rescinded from Sta. 13+70 to Sta. 28+70.
- April 27, 1938 showing authority for Dike Extension 642.3 L.B. cancelled.
- May 23, 1938 showing changed strength of Dike 642.3 L.B., to conform to letter of even date.
- June 25, 1938 showing portion of Dike 642.3-A L.B. and portion of Revetment 643.1 R.B. rescinded to conform to letter of even date.
- Aug. 12, 1938 showing Dike Ext. No. 643.6, L.B. deleted & showing changed length of Revetment No. 645.3, L.B. & changed length of Revetment No. 643.1, R.B.
- Dec. 5, 1938 showing authority for construction of uncompleted portions of Revetment 645.3 L.B., Revetment 643.1 R.B., also Marker Clumps on Dikes 646.5, 646.4, 646.4-A and 646.3 all R.B., rescinded, to conform to letter of even date.

