



P O T T A W A T T A M I E C O U N T Y

D O U G L A S C O U N T Y  
N E B R A S K A

**NOTE:**  
 Revement 668.65 damaged from downstream  
 face of O.P.P.D. intake bldg. to about Sta. 6135  
 Tax and mattress damaged and what rock  
 remains appears to be dumped stone. No definite  
 top of piling found.

SCALE: 1 INCH=100'

**DETAIL**  
 REVEMENT 669.65

**DETAIL**  
 DIKE 670.3 (PARTIAL)  
 Bank Protection by others 229'02"  
 Water Edge 330'  
 Riverward edge of old Crib Dike (buried) 186'56" (35.48)  
 320'50'30"  
 5'88'  
 6'04'  
 2'80' Conc.  
 Bankline 4'07'  
 4'50'  
 SCALE: 1 INCH= 100 FEET

2801000W  
**MISSOURI RIVER BANKS**  
 State Surveyors Office, State of Nebr.  
 Taken From U.S. Army Engineer Plans.  
 Showing Section Lines, Date: 8-1-1962  
 Sheet No. 65 Scale: 1" = 400'